



Syscal switch check list

Device

Syscal switch (Tx and Rx fully charged)
USB Cable with Syscal Plug
Syscal user's manual
[Safety instruction leaflet](#)

Softs

CD IRIS Instruments with USB Driver
RES2/3DINV Dongle
Laptop with [Electre Pro](#) + [Prosys](#) installed

Tools

Security Pack
Electrode Tester
Battery Tester
Switch Pro
WiConnect device
SD Card Reader

Accessories

Battery chargers + adapters if necessary
12V External Battery fully charged
External Battery Cable
(Red & Black) Alligator Clip (Red & Black)
Stainless steel Electrodes or Unpolarizable Electrodes
Cord Clip (3 + number of channels + extras)
Cables (orange or yellow)
Connecting boxes (if necessary)
Reels of cable (1 for pole-dipole, 2 for pole-pole)
Measuring tape (non metallic)
GPS
Hammer
Voltmeter with two 1m cables
Salted water + bentonite